

Almost New Years already!!

WE SELL
& REPAIR:


STEAM
CLEANERS

PRESSURE
WASHERS

PAINT
SPRAY
EQUIPMENT

COMMERCIAL
FLOOR
EQUIPMENT

STANDBY
GENERATORS



SMALL ENGINES

SMALL TO
MEDIUM SIZE
CONSTRUCTION
EQUIPMENT

AND WE SELL
PARTS TOO!



1721 SE Stephens St.
Roseburg, Oregon 97470

Phone: 672-3409

Fax: 229-3409

Email: mail@timallenequipment.com

MERRY CHRISTMAS & HAPPY NEW YEAR!

I would like to thank each of you for your continued support and patronage! This year saw a lot of changes for us, most notably the new location at 1721 SE Stephens St., here in Roseburg. We've now got much more room, and secure parking, as well as some showroom space. If you've not had the chance to stop by yet, I encourage you to come over and take a look around! There are also going to be a couple of new faces around to help us keep up with the growth we've experienced this year:

- Phil Marsh— Phil will be our new outside sales rep.. He comes to us with many years of experience in the building maintenance trade, both working for others and as his own business.
- Dale Jones— Dale is going to be helping in our service department. Dale has many years of experience in the small engine field as well as time working with industrial equipment in a mine setting.

We're excited about the year to come, and hope that you have a happy and prosperous new year. We look forward to helping in any way we can.



New car wash equipment we installed at Winston Carwash. Give them a try sometime, they work great and I'm certain they'd appreciate the business!

EQUIPMENT EXPOSED TO FREEZING TEMPERATURE??

At our house the temperature read 11° this morning, fortunately we left the water running a touch so no major pipe problems!

If you're concerned your equipment may *BE* frozen, **do not attempt to run/start it**. Move it to a warm (not hot) location and let it slowly thaw out. When

everything is warm to the touch, you can attempt to run it. Some not so obvious symptoms that may indicate hidden damage:

Paint sprayers—pressure control problems like a wide on/off pressure band. Prime spray valve not working correctly.

Pressure washers—vibration in the hose, reduced pressure at the tip, temperature control not working correctly.

Car or truck—thermostats damaged by freezing generally result in your car taking a long time to warm up in the morning, if they reach normal temp at all .



1721 SE Stephens St.
Roseburg, Oregon 97470

When you NEED it right the first time!



January/February Special!!
Bring in this coupon for...
10% off labor on one invoice!
(Not to be combined with other specials)
Expires 2/28/09

To request a copy of our pressure washer parts catalog call toll free (877)-672-3409 or email: mail@timallenequipment.com

IT GOT COLD IN A HURRY THIS YEAR!

With the economy being what it is, a lot of folks are choosing to spend more time closer to home. We hope you've had a chance to rekindle some old friendships, or had a chance to get back in touch with family that you've been too busy to spend as much time with as you'd like.

Some thoughts that keep bouncing around in my head are what kinds of hobbies or entertainment are most suited for the current economic climate. Again keeping it close to home seems to be the order of the day. Perhaps some painting or photography. Yes the economy is tough right now, but maybe that isn't so bad after all.



Overlooking Umpqua Valley

No Bake Peppermint Cheese Cake

- 1 8oz package cream cheese (room temp.)
- 1 pint whipping cream
- 3 medium candy canes (crushed)
- 1 Graham Cracker Pie crust shell

Whip the cream, add cream cheese and mix until smooth, then stir in candy cane pieces. Pour into pie shell and chill overnight.